**Document: #HT000025**

Document Title: Reset Ribbon Take-Up

Product(s): Ti-1000 TEC Printer

Procedure:

With power **"OFF"**, hold down **"FEED"** and **"PAUSE"** buttons on the control panel.

Turn power **"ON"** while holding the buttons. **"DIAG V____"** will be displayed on panel.

Press the **"FEED"** button 1 time, and display will read **"(2)"**

PARAMETER SET

Press **"PAUSE"** button repeatedly until **"RIBN ADJ (FW) +0"** shows.

Press **"RESET"** button to **"-3"** is displayed.

Press **"PAUSE"** button until **"(2) PARAMETER SET"** is displayed.

Turn power **"OFF"** and wait till all lights on display panel go out.

Power now can be turned **"ON"** with new ribbon take-up speed.

Note: If a Parameter Clear is done, this speed will go to default setting of "0".