

How To

Service Documents from APPI

Document: #HT000142

Document Title: Locate Fuses on Xi3 Power Supply

Product(s): Ti-1000Z

Procedure:

The Xi3 Power Supply has two fuses, marked above as FUSE 1 & FUSE 2.

1. FUSE 1 is a 5A 250V fast blow fuse.
2. FUSE 2 is a soldered in fuse.

Both can be checked with an Ohmmeter.

The AC Input to the power supply is at the 2-pin white connector marked AC above. This power supply can handle 100-240vac.

The black 4-pin plugs marked DC above will have a red and a black wire. The black is ground and the red is 5VDC.

