


Document: #HT000010

**Document Title: Check Zebra Power Supply** 


Product(s): T-1000

**Procedure:** 

Logic Board:







Turn Main Power off. Disconnect the Power Connector from the Logic Board. Measure the voltage between the Black and Red wires in the connector; it be +5VDC. Measure between Black and Yellow wires; the voltage should be +24VDC.

Note: If you do not get these voltages, check the connections and/or change the Power Supply.