



# How To

Service Documents from APPI

**Document: #HT000050**

**Document Title: Adjust Dancer to be Parallel to Bagger**

**Product(s): T-1000**

**Procedure:**

Sighting with the shaft on rear of Bagger, make sure Dancer Roller is parallel to the Bagger shaft.




If the shafts are not parallel, loosen 2 Socket Head Bolts on Dancer Frame and move Dancer Frame Fore or Aft to parallel Dancer Roller with Bagger Shaft.



# How To

Service Documents from APPI



If not properly adjusted, bags will not feed straight.