

Document: #HT000061

Document Title: Set Up EasyLabel

Product(s): Ti-1000Z

Procedure:

This HOW TO shows the steps to set up labels for the APPI TIZ printers. This can be done in two ways, and both ways will be shown. This procedure assumes that the ZDesigner printer driver is already installed, and the printer is already connected to the computer.

Set Up a Printer Internally in EasyLabel



E Printer Configura	ation	×
General Advanced		
Printer Man <u>u</u> facturer	Zebra	
Printer <u>M</u> odel	110Xi4 203 DPI	
Printer <u>N</u> ame	WhateverYouWantHere	
Printer Description	WhateverYouWantHere	
Type of port	5-USB V	
<u>B</u> idirectional	Yes	
USB Port	USB001	
<u>C</u> utter	0-Not Installed	
Calendar Option	No	
Select the type of port Serial is for standard s	t where the printer is connected.	
Parallel is for standard	I parallel LPT ports.	
or to use a local W	/indows port and the Windows spooler.	
In 13 to princes of prin		
	OK Cancel	

General:

Set the General settings accordingly. Type of port depends on how the printer is connected to the computer.



Advanced:

All these settings are optional.

EasyLabel Internal Printer Settings

Paste	Ctrl-V
Change Format Specification	
Choose All Fields	
Rotate	
Display grid	
Snap to grid	
Zoom Level	>

Right click an empty area of the label.

EL Form	nat EL Test						×
General	Printer Settings	Options Pa	ge layout	Cutter	Page Head	er RFII	D
Printer <u>M</u> o	del	17 - 110Xi4	203 DPI				
D <u>e</u> fault Pr	inter	WhateverYo	ouWantHe	re			
Descriptio	n]
Display <u>O</u> r	ientation	1-Leading e	dge Down	1			-
Fields curr	rently defined	NONE					
<u>A</u> uto Field	Name	Yes					
Save Bad	kup Format	No					
Save Print	t Image	No					
Tracking I	Report by Batch	No					
	Select Cancel (ESC) to QUIT.	, or press a	any other	key to CHAN	3E data	
							Change Cancel

General: Set up as neces

Set up as necessary for your application.

🗉 Forn	nat EL Test							×
General	Printer Settin	gs Options	Page layout	Cutter	Page Header	RFID		
Print <u>M</u> od	e	R-Rewind m	ode 🗸 🗸					
Print <u>D</u> ark	iness	20.0						
Label <u>O</u> ffs	set	0						
<u>P</u> resentat	ion Position	0						
Print <u>S</u> pee	ed	5-6.0"/sec.						
<u>B</u> ackfeed	Speed	1-2.4"/sec.						
		C-	la et the a destinad		4.			
		Se	lect the desired	i print mo	de.			
								\parallel \times \parallel
								$ $ \setminus
							ОК	Cancel

Print Settings:

Print mode must be rewind. Darkness can be anything that gives a good print. Print speed can be anything that gives a good print.

E Format EL Te	st						×
General Printer S	Settings Options	Page layout	Cutter	Page Header	RFID		
Pass Through							
Download <u>F</u> onts	No						
<u>Flip</u> Format	No						
<u>R</u> everse Image	No						
<u>M</u> irror Image	No						
Job Separator	0						
Pause Option	0 - Do not pause						
Salaat	Canaal (ESC) to C		u other l	ente CHANGE	data		
Select	Caricel (ESC) to G	torr, or press art	y other r	ley to CHANGE	udid		$ \setminus / $
						Change	Cancel

Options:

These are settings are optional except Pause option.

How To
Service Documents from APPI

E Format EL Test							×
General Printer Settin	gs Options	Page layout	Cutter	Page Header	RFID		
<u>G</u> aps Between Labels	No						
Print Area <u>H</u> eight	4.02						
Print Area <u>W</u> idth	4.00						
Number <u>A</u> cross	1						
Vertical Separation	4.12						
<u>M</u> argin Width	.00						
Background Image]	
Select Care	al (ESC) to 0		unu ethor	key te CHANCE	data		
Jelect Carl	UEI (LUC) 10 G	on, or press a	any other	Key to CHANGE	uala		
						Change	Cancel

Page Layout:

No Gaps Between Labels. Width should always be 4 (the same as the ribbon width). Number Across always 1. No Margin Width.

ZDesigner Printer Driver

Paste	Ctrl-V
Change Format Specification.	
Choose All Fields	
Rotate	
Display grid	
Snap to grid	
Zoom Level	>

Right click an empty area of the label.

🖲 Format EL Test		×				
General Printer Settings	Options Page layout Cutter Page Header RFID					
Printer <u>M</u> odel	2 - ZDesigner 110Xi4 300 dpi (W)					
D <u>e</u> fault Printer	ZDesigner 110Xi4 300 dpi					
Description	WhateverYouWantHere					
Display Orientation	3-Leading edge Up					
Fields currently defined	NONE					
<u>A</u> uto Field Name	Yes					
Save Backup Format	No					
Save Print Image	No					
Tracking Report by Batch	No					
If desired, ente	er DESCRIPTIVE TEXT to identify or document the format.	$\overline{\langle}$				
	OK	əl				

General:

Choose the ZDesigner printer driver listing you are using. Set up as necessary.

🗉 Format EL Test				×
General Printer Setting	gs Options Page layout	Cutter Page Header	RFID	
Bar/Space Adjustment	1.0			
<u>R</u> esolution	1 - 300 DPI			
Color Selection	Monochrome (Black/Whi	ite)		
Additional <u>O</u> ptions	Yes V No Yes			
Select 'Yes' only if you select 'No'. Changing t windows applications.	need to set PRINTER SPE hese options will not effect	CIFIC options not shown a the printer settings for othe	above, otherwise er formats or	
			ОК	Cancel

Printer Settings:

Leave Bar/Space at 1.0 Resolution will be set by the printer.

Color selection should be Monochrome.

To access the ZDesigner driver settings click Yes under additional options.

	Barcode Font	s			Comman	d Font	3
Custom Commands Impo		ort/Export	t settings	To	ols	About	
Options	Advanced	Setup	Dithe	ring	Stocks	Print	ter Memory
Settings							
Ν	o. Of Copies:		1				
5	peed:		6	~	"/s		
0)arkness:		20	~]		
	tocke:		Lloon dei	fined]		
`			User de	nnea			~
Paper For	mat						
(_) <u>c</u> m			<u>p</u> ortr	ait		
() <u>m</u> m		ABCD		scape		
0) inch	1	2945276	<u>r</u> otat	e 180°		
Size —							
<u>v</u>	<u>V</u> idth:	4.00					
Ŀ	<u>l</u> eight:	4.00					
Unprintab	le Area —						
L	<u>e</u> ft:	0.00		Top:	[0.00	
F	Right:	0.00		 Bottom	: [0.00	
					L		

Options:

Settings No. Of Copies: 1 Speed: 6 Darkness: 20 Stocks: User Defined

Paper Format

- Inch
- portrait

Rotation is optional

Size:

Width: 4.00 Height: Anything you need.

Unprintable Area: All should be zero.

👼 ZDesigner 110Xi4 300 dpi	i Properties
Barcode Fonts	Command Fonts
Custom Commands Im	port/Export settings Tools About
Options Advanced Setup	Dithering Stocks Printer Memory
Use printer settings Operation Mode	
◯ Tear off	○ RFID
○ Rewind	◯ Cutter
Peel Off	Group Quantity: 0
 Applicator Stream 	◯ Advanced **
Mirror Image	Inverse
Media Type	,
Thermal Transfer	 Thermal Direct
Tracking Mode	,
 Continuous 	O Mark Sensing
Web Sensing	
Adjustment	
Тор	0.00 inch
Tear Off	0.00 inch
Left Position	0.00 inch
** Only valid for use with Lab	eling Software
Applicator	Other Calibrate
	OK Cancel Help

Advanced Setup:

Operation Mode • Applicator

Click the Applicator button on the bottom.

Applicator Setup	? ×
Operation mode	
<pre> • • • • • • • • • • • • • • • • • • •</pre>	O Maximum throughput
Reprint on error	
Application mode	
Ooff	◯ Signal HIGH 20ms
Signal HIGH	◯ Signal LOW 20ms
Signal LOW	
Start signal	
Pulse mode	O Level mode
Application label	
Error mode	◯ Feed mode
Other settings	
Reprint mode	Ribbon low mode
	Close

Applicator Setup:

Application mode needs to be:

• Signal HIGH

Click Close.

	barcoue Fori	S		Command	l Fonts	
Custom C	Commands	Import	Import/Export settings Too		ls	About
Options	Advanced	Setup	Dithering	Stocks	Printe	er Memory
	inter settings					
Operation	Mode					
) Tear off			FID		
(Rewind		00	utter		
() Peel Off		Grou	p Quantity:	0	
(Applicator		⊖ A	dvanced **		
() Stream					
Ľ	Mirror Image	e	_ Ir	iverse		
Media Typ	pe					
(Thermal Tra	ansfer	ОТ	hermal Direc	t	
Tracking	Mode					
0	Continuous		OM	lark Sensing		
() Web Sensir	ng				
Adjustmer	nt					
Т	ор	0.00) inch			
Т	ear Off	0.00) inch			
L	eft Position	0.00) inch			
** Only v	alid for use wi	th Labelin	g Software			
	Applica	ator	Other		Calib	rate

Back in the Advanced Setup Tab:

Operation Mode

• Rewind

Media Type

• Thermal Transfer

Tracking Mode

• Continuous

Adjustment All zero.

Click Dithering tab.

👼 ZDesigi	ner 110Xi4 30	00 dpi Pr	operties				×
Barcode Fonts				Command Fonts			
Custom C	ommands	Import	t/Export se	Export settings Tools		About	
Options	Advanced	Setup	Ditherin	g	Stocks	Prin	ter Memory
Dithering (((ype) Smooth) Scanned) Detail) None					5	
			OK		Cancel		Help

Dithering:

Dithering typeNone.

Done. Click OK.

EasyLabel is now set up to print with the ZDesigner printer driver.